



## Calibrating a Probe Thermometer

When calibrating thermometers, handle it gently, because rough handling or dropping will cause it to lose calibration.

### When:


- Calibrate each thermometer frequently.
- Weekly or at least once a month,
- Or after it has been dropped.

### How:

1. Fill a medium glass with ice.
2. Add water.
3. Place thermometer in ice
4. Wait a few minutes
5. After a few minutes, thermometer should read 32 F.

### If thermometer does not read 32° F.:

1. Leave thermometer in water
2. Using pliers turn hex nut until needle reads 32 F.
3. Wait a few minutes
4. Repeat step 2 if thermometer isn't reading 32 F.



32 ° F

